

CENTRAL INTELLIGENCE AGENCY

REPORT NO. [REDACTED]

## INFORMATION REPORT

CD NO.

COUNTRY USSR ( Gorki Oblast)

DATE DISTR. 7 Nov. 1949

SUBJECT Krasnaya Etna Plant in Gorki

NO. OF PAGES 2 PCN

PLACE 25X1C

NO. OF ENCL. 1 202


ACQUIRED [REDACTED]

RETURN TO CIA LIBRARY

DATE OF INFO. 4

SUPPLEMENT TO REPORT NO.

25X1X



1. Plant area: 1,600x2,600 feet.
2. Traffic facilities: The plant had spur tracks, but there were no track ramifications in the plant area. There was an access road from the highway to the plant.
3. Plant installations (the following enumerations correspond to the numbers of the sketch):
  1. Administration building, three-story stone building, 65x100x40 feet.
  2. Guardhouse.
  3. Nail and spring department. Two-story steel structure, about 500x130x20 feet.
  4. Motorcycle department, two-story steel structure, about 330x160x20 feet.
  5. Rolling mill, two-story steel structure, 650x160x20 feet.
  6. "Wire-drawing shop, two-story steel structure, 500x160x26 feet.
  7. Annealing department, two-story steel structure, 500x160x26 feet.
  8. Depot, one-story wooden structure, 160x30x26 feet.
  9. Hardening shop, two-story stone building, about 50x150x26 feet.
  10. Bolt and rivet department, two-story steel structure, about 330x160x26 feet.

DO NOT CIRCULATE

CLASSIFICATION CONFIDENTIAL/CONTROL-US OFFICIALS ONLY

STATE	NAVY	NSRB	DISTRIBUTION						
ARMY #	AIR #	FBI	Document No. 2						
			No Change In Class. <input checked="" type="checkbox"/>						

 Declassified

CONFIDENTIAL-CONTROL/US OFFICIALS ONLY

25X1A

CENTRAL INTELLIGENCE AGENCY

- 2 -

11. Sheet metal band department, two-story steel structure, about 650x160x26 feet.

4. Work force and working time: About three thousand workmen were employed in October 1946. Work was done in three 8-hour shifts.

5. Power and raw materials: Power was supplied from GORKI (56°20'N/44°00'E). Iron and steel came from SVERDLOVSK (allegedly smelted scrap stocks).

5. Production:

Motorcycles  
Steel and spring wires  
Nickelene wires for heating implements  
Bolts

25X1A Nails, springs, and spring washers.

Comment:

This report confirms a previous report, with which the annexed sketch is also in agreement.

1 Annex: Plant Layout of the Krasnaya Ztta Plant in GORKI

CONFIDENTIAL-CONTROL/US OFFICIALS ONLY